





Visual Installation Instructions DualDrop™ Cables with FastAccess™ Technology





← Scan the code with your mobile device to access full SRP



WARNING: Corning Optical Communications recommends the use of safety glasses (spectacles) conforming to ANSI Z87, for eye protection from accidental injury when handling cables or working with fibre.



WARNING: Never look into the end of a fibre or connector that may be carrying laser light. Laser light can be invisible and can damage your eyes. Viewing it directly does not cause pain. The iris of the eye will not close involuntarily as when viewing a bright light. Consequently, serious damage to the retina of the eye is possible. Should accidental exposure to laser light be suspected, arrange for an eye examination immediately.



Use safety gloves when handling cable.



Maintain minimum bend radius specified in SRP.



Do not exceed installation loads specified in SRP.



It is recommended to pull on the bare cable end of the pigtail.



Be careful not to pull 2.9mm cable out of 5mm cable.



It is recommended to use Telenco 7593 drop wire clamps for aerial applications.



Span is typically 50m max depending on local wind and ice loads.

CORNING